



FIG. 3




FIG. 2




FIG. 5




FIG. 4




FIG. 6




FIG. 3

FIG. 7




FIG. 11





FIG. 12



109070 2440660

FIG. 7A




FIG. 8




FIG. 9





FIG. 10



709040 24400552

FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18






FIG. 19




FIG. 20




FIG. 21 is a cross-sectional view of the door assembly.




FIG. 21




FIG. 22




FIG. 25C





FIG. 25B



250

FIG. 25A

